



ऑपरेशनल ऑफिस कंप्लेक्स,
चिरंजीबपुर, हल्दिया-721604,
जिला-पूर्ब मेदिनीपुर.

SYAMA PRASAD MOOKERJEE
PORT, KOLKATA
हल्दियागोदीपरिसर
HALDIA DOCK COMPLEX
शिपिंगएंडकार्गोहैडलिंगप्रभाग
T.O. (Sh&CH) Division



Operational Office Complex,
Chiranjibpur, Haldia-721604,
Dist. Purba Medinipur.

No: T.O.(Sh&CH)/19/1315

Date : 24.08.2022

व्यापार परिपत्र / TRADE CIRCULAR

Sub: Proactive Action / Measures for Prevention and Control of Accidents Inside Dock Zone of HDC.

It has been noticed that some vehicles working inside the dock are having broken Break light, Turning Indicator, and Reverse Horn thus may contribute to accident and pose great danger to the safety & health of Dock Workers working inside Dock Interior Zone of Haldia Dock Complex. The matter has been viewed seriously by Inspectorate of Dock Safety.

In order to avoid accidents and to keep safe working environment inside Dock Interior Zone, it is hereby advised that all vehicles working inside dock should strictly comply to the requirement of having proper Break light, Turning Indicator, and Reverse Horn.

It is advised that all Transporters may take proactive action / measures for prevention and control of accidents inside Dock Zone of HDC, failing which strict action as deemed suitable by the Appropriate Authority will be initiated against the concerned Transporter.

The above is for strict compliance please.

11.8.22
24/8/22

प्रियंकर सरकार / Priyankar Sarkar
सहायक प्रबंधक (शिपिंग एवं का. है.) / Assistant Manager T.O(Sh & CH)
कृते वरिष्ठ उप प्रबंधक (शिपिंग एवं कार्गो.)/For Sr Dy.Manager TO(Sh& CH)

CC: Dy. Manager, TO(Sh&CH): For Kind information please.