MRN/HMR/DH/175

S.M.P. KOLKATA

एस॰एम॰पो॰ कोलकाता H.M.(R)'S OFFICE DIAMOND HARBOUR APRIL.'2024 Dated 27.02.2024

ESTMATED FRESH WATER DRAFT FORECAST FOR THE MONTH OF April'2024 FOR

DIAMOND HARBOUR FOR VESSELS				LS OF 12KTS. & OVER (SUBJECT TO ALTERATION)
INWARD:				NOTES
Date	A	В	С	
1st	7.8	8.0	8.2	Calculated for 12 kts River speed. Indward Draft to be reduced
2nd	7.6	7.8	8.0	by 0.1 mtr for every knot below 12 kts. Outward draft to be redu-
3rd	7.6	7.8	8.0	ced by 0.2 mtr for every knot below 12 knots.
*4th	7.3	7.5	7.7	
5th	7.6	7.8	8.0	
6th	8.0	8.2	8.4	2. LOA Category :
7th	8.3	8.5	8.7	A) Above 180 mtrs to 200 mtrs
8th	8.5	8.7	8.9	B) 160 mtrs to 180 mtrs.
9th	8.6	8.8	9.0	C) Below 160 mtrs.
10th	8.6	8.8	9.0	
11th	8.5	8.7	8.9	3.a) Maximum size of vessel up to LOA 200 mtrs.
12th	8.3	8.5	8.7	b) Maximum permissible draft up to 9.5 mtrs.
13th	8.1	8.3	8.5	
14th	7.8	8.0	8.2	4. As there is no anchorage between Sagar and Diamond Harbour/
15th	7.6	7.8	8.0	Kulpi, all vessels to ensure that their engines and steering etc. are
16th	7.4	7.6	7.8	in good working order.
*17th	7.2	7.4	7.6	
18th	7.3	7.5	7.7	F. All vessels are required to be to the service of
19th	7.5	7.7	7.9	5. All vessels are required to have two serviceable bower anchors.
20th	7.8	8.0	8.2	In view of strong tides at anchorage, Masters to ensure that the
21st	8.0	8.2	8.4	anchor chains, windlass etc. are in good working order.
22nd	8.1	8.3	8.5	6 A LS. Dilet plug of all vessels are required to be enrational
23rd	8.2	8.4	8.6	6. A.I.S. Pilot plug of all vessels are required to be oprational.
24th	8.3	8.5	8.7	7 December Bodford 6.4 mtrs 9.1 Maragalia 5.2 mtrs 1.CTV.6.0
25th	8.3 8.3	8.5 8.5	8.7 8.7	7. Based on Bedford -6.4 mtrs. & L.Maragolia -5.3 mtrs. LSTX-6.0
26th 27th	8.3	8.5	8.7	8. Maximum of three vessels may be accommodated at ancho-
27th	8.2	8.4	8.6	rage subject to tidal/weather conditions. In strong tides/adverse
29th	8.1	8.3	8.5	weather or for any other reason, number of vessels at anchorage
30th	8.0	8.2	8.4	may be reduced.
30011	0.0	0.2	0.4	linay be reduced.
OUTWARD				9. Forecast subject to alterations.
		7.0	7.0	o. Forceast subject to alterations.
1st	7.4	7.6	7.8	
2nd 3rd	7.3	7.5	7.7	from Cogar DilatA/TC Station
4th	7.3 7.4	7.5 7.6	7.7 7.8	from Sagar Pilot/VTS Station.
5th	7.4	7.7	7.8	11. Inward vesels should report their ETA Sandheads to Pilot
6th	7.6	7.7	8.0	Station and ask for pilotage instructions between ECLV (21*04'N,
*7th	7.5	7.7	7.9	88*11'12"E) and Gasper Channel before proceeding up.
8th	7.7	7.7	8.1	1
9th	7.8	8.0	8.2	12. Assistance is available from VTMS Station at Haldia/Sagar
10th	7.8	8.0	8.2	on VHF Channel 16/68 above Lower Gasper Light Vessel.
11th	7.8	8.0	8.2	and the second s
12th	7.7	7.9	8.1	13. Inward Vessels anchoring at Sandheads to keep clear the
13th	7.6	7.8	8.0	shipping lane.
14th	7.5	7.7	7.9	, '' ~
15th	7.4	7.6	7.8	14. Master to check with Sagar VTS for any changes in the approach
16th	7.3	7.5	7.7	channel / way points to the Pilot Boarding Ground (PBG) before
17th	7.2	7.4	7.6	entering the channel.
18th	7.3	7.5	7.7	
19th	7.3	7.5	7.7	15. Proper anchor watch & VHF watch on Channel 16 to be
20th	7.4	7.6	7.8	maintained and M/E to be kept on short notice at the anchorage.
*21st	7.5	7.7	7.9	_
22nd	7.6	7.8	8.0	
23rd	7.6	7.8	8.0	
24th	7.7	7.9	8.1	
25th	7.7	7.9	8.1	Sd/-
26th	7.7	7.9	8.1	(D Sengupta)
27th	7.7	7.9	8.1	HARBOUR MASTER(RIVER)
28th	7.7	7.9	8.1	बदरगाह मास्टर (नदा)
29th	7.7	7.9	8.1	
30th	7.6	7.8	8.0	
-				