1. Mode of selection:- Written Test.

Full Marks - 50, Qualifying Marks - 25

2.

| SI. | Required inputs | Turner | Machinist |
|-----|---|--|---|
| No. | | | |
| a) | Syllabus | The Operation and Maintenance of different types of Lathe Machine, Measuring instruments. | The Operation and Maintenance of different types of Shaping Machine, Drilling Machine, Measurement instruments. |
| b) | Structure of Question Paper | Technical 90% and General Knowledge 10% | Technical 90 % and General Knowledge 10% |
| c) | Type of Question Paper | Objective type | Objective type |
| d) | Degree of difficulty of Question Paper | Moderate | Moderate |

3. The Model question paper along with answer are given below:

<u>TURNER</u>

- When the tool is feed parallel to the rotation of the job, it will produce surface. (Cylindrical / Conical / Spherical)
 Ans. Cylindrical.
- The function of lead screw is for making _____ (Drilling / Boaring / Thread cutting)
 Ans. Thread Cutting
- The lathe carriage serves _____ purpose. (Guiding / Feeding / Supporting / All of the above)
 Ans. All of the above.
- 4. _____ is the also known as tool rest. (saddle / cross slide / compound rest).

Ans. Compound rest.

5. What is least count of vernier caliper?Ans. Minimum measurement possible by vernier caliper.

MACHINIST

- What is least count of vernier caliper?
 Ans. Minimum measurement possible by vernier caliper.
- 2. Shaping machine is use for making _____? (Key way / Drill / Bore) Ans. Key Way.
- 3. The tip angle of a Common Drill is _____ (110 deg. / 118 deg. / 126 deg.) Ans. 118 deg.
- The coolant is for drilling the Aluminum job _____ (Dry air / Kerosene / Mineral Oil)
 Ans. Kerosene.
- 5. What is the name of Prime Minister of India? Ans. Shri Narendra Damodardas Modi.